



Locomotive Release from Shop Form

To be completed on every engine released from the Shop

I have reviewed the work packet for locomotive 5017 on this date 5-24-11 and take no exception to applicable laws, rules and or MMA standards, policies and standards.

pin pin said up #2 LEH



UNIT 5016

DATE _____

Service Operations

THROTTLE 8 INBOUND LOAD TESTS

Eng RPM (900)	EMD	_____	Lube Oil Pres	_____
Eng RPM (1050)	GE	_____	Water Temp	_____
Horsepower		_____	Overspeed Setting	_____
Volts (5.3)	B-23	_____	RACK SETTING	_____
Volts (7)	C-30	_____		
Volts (720)	B-39	_____		

THROTTLE #1 STALL TEST

OP Mode	(PWR)	_____	NOT APPLICABLE TO B-23 AND C-30
AMPS	(300)	_____	
MGA	(1220)	_____	
Charging Rate	(70v)	_____	

TL 24T

Throttle 1	(1V)	_____
Throttle 2		_____
Throttle 3		_____
Throttle 4		_____
Throttle 5		_____
Throttle 6		_____
Throttle 7		_____
Throttle 8	(72V)	_____

PINTON PWA SE 12BP -5-25-71



B-23, B-39, C-30, GP-7 UNSCHEDULED

UNIT:

ITEM	MECHANICAL <i>-Running Mechanical</i>	WORKED BY:
	INSPECT ENGINE OVERHEAD (WITH ENGINE AT IDLE):	
	PROPER LUBRICATION? FUEL LEAKS? CAM ROLLER ROTATION? ETC.	
	INSPECT FUEL SYSTEM HOSES AND PIPES FOR LEAKS	
	INSPECT COOLING SYSTEM:	
	A: CHECK HOSES AND PIPES FOR LEAKS	
	VISUALLY INSPECT AIR COMPRESSOR FOR WATER, AIR OR OIL LEAKS	
	TEST AIR BRAKE EQUIPMENT PER RULE 212	
	PERFORM PENALTY BRAKE TEST	
	CHECK FLUID LEVELS BEFORE LOADING:	
	A: ENGINE OIL	
	B: COOLING WATER	
	C: AIR COMPRESSOR OIL	
	TEST OPERATION OF THE FOLLOWING DEVICES:	
	A. BELL	
	B. SANDERS (FORWARD, REVERSE, EMERGENCY)	
	C. RADIATOR SHUTTERS	
	INSPECT AIR COMPRESSOR GOVERNOR SETTING. 135 TO 145 PSI	
	INSPECT SAFETY POP. 155 PSI	



UNIT _____

DATE _____

Service Operations

THROTTLE 8 OUTBOUND LOAD TESTS

Eng RPM (900)	FMD	_____	Lube Oil Pres	_____
Eng RPM (1050)	GF	_____	Water Temp	_____
Horsepower		_____	Overspeed Setting	_____
Volts (5.3)	B-23	_____	RACK SETTING	_____
Volts (7)	C-30	_____		
Volts (720)	B-39	_____		

THROTTLE #1 STALL TEST

OP Mode	(PWR)	_____	
AMPS	(300)	_____	
MGA	(1220)	_____	NOT APPLICABLE TO B-23 AND C-30
Charging Rate	(70v)	_____	

TL 24T

Throttle 1	(1V)	_____
Throttle 2		_____
Throttle 3		_____
Throttle 4		_____
Throttle 5		_____
Throttle 6		_____
Throttle 7		_____
Throttle 8	(72V)	_____

C.C.P.'s Check Base For Pressure on out Board

Unit: 5016

Date: 5-24-11

DEFECTS FOUND DURING INSPECTION

DEFECT <u>wrist pin froze on pistons</u> <u>Cracked crown on pistons</u> <u>Cyl. was also backd</u>	INSPECTED BY: <u>K. Hickey</u> <u>D. Black</u>
REPAIR <u>Changed wrist pin replace with use pin</u> <u>micro OK New piston replacement and</u> <u>Cyl. #2</u>	CORRECTED BY: <u>K. Hickey</u> <u>D. Black</u>

DEFECT _____	INSPECTED BY: _____
REPAIR _____	CORRECTED BY: _____

DEFECT _____	INSPECTED BY: _____
REPAIR _____	CORRECTED BY: _____

DEFECT _____	INSPECTED BY: _____
REPAIR _____	CORRECTED BY: _____

DEFECT _____	INSPECTED BY: _____
REPAIR _____	CORRECTED BY: _____

Unit: _____

Date: _____

DEFECTS FOUND DURING INSPECTION

DEFECT _____ _____ _____	INSPECTED BY: _____ _____
REPAIR _____ _____ _____	CORRECTED BY: _____ _____

DEFECT _____ _____ _____	INSPECTED BY: _____ _____
REPAIR _____ _____ _____	CORRECTED BY: _____ _____

DEFECT _____ _____ _____	INSPECTED BY: _____ _____
REPAIR _____ _____ _____	CORRECTED BY: _____ _____

DEFECT _____ _____ _____	INSPECTED BY: _____ _____
REPAIR _____ _____ _____	CORRECTED BY: _____ _____

DEFECT _____ _____ _____	INSPECTED BY: _____ _____
REPAIR _____ _____ _____	CORRECTED BY: _____ _____

Description of Work Performed

Locomotive ID

5016

Time Started

Time Finished

changed #2 wrist pin, piston and cly,
new gaskets installed on exhaust and
water pipes, new gasket installed on air box
and water line. Four new cyl. bolts
installed. Check main rod for straightness ok
Bad compression #2 90 lbs.

K. Hussey
D. Black

Washed unit

DAVE BLACK

ADDED TEMPO

KIM HUSSEY

ADDED 4 1/2 oil - DAVE BLACK

WOULD NOT SELF LOAD -

